






| X9 20S辅助触点 | | | |
|------------|----|-----|----|
| 对侧 | 线号 | 端子号 | 线号 |
| | | 1 | |
| | | 2 | |
| | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 6 | |
| | | 7 | |
| | | 8 | |
| | | 9 | |
| | | 10 | |
| | | 11 | |
| | | 12 | |
| | | 13 | |
| | | 14 | |
| | | 15 | |
| | | 16 | |
| | | 17 | |
| | | 18 | |
| | | 19 | |
| | | 20 | |
| | | 21 | |
| | | 22 | |
| | | 23 | |
| | | 24 | |
| | | 25 | |
| | | 26 | |
| | | 27 | |
| | | 28 | |
| | | 29 | |
| | | 30 | |
| | | 31 | |
| | | 32 | |
| | | 33 | |
| | | 34 | |
| | | 35 | |

| X11 CT引线 | | |
|----------|----|-----|
| 对侧 | 线号 | 端子号 |
| | | 1 |
| | | 2 |
| | | 3 |
| | | 4 |
| | | 5 |
| | | 6 |
| | | 7 |
| | | 8 |
| | | 9 |
| | | 10 |
| | | 11 |
| | | 12 |
| | | 13 |
| | | 14 |
| | | 15 |
| | | 16 |
| | | 17 |
| | | 18 |
| | | 19 |
| | | 20 |
| | | 21 |
| | | 22 |
| | | 23 |
| | | 24 |
| | | 25 |
| | | 26 |
| | | 27 |
| | | 28 |
| | | 29 |
| | | 30 |
| | | 31 |
| | | 32 |
| | | 33 |
| | | 34 |
| | | 35 |
| | | 36 |
| | | 37 |
| | | 38 |
| | | 39 |
| | | 40 |

| X11 CT引线 | | |
|----------|----|-----|
| 对侧 | 线号 | 端子号 |
| | | 41 |
| | | 42 |
| | | 43 |
| | | 44 |
| | | 45 |
| | | 46 |
| | | 47 |
| | | 48 |
| | | 49 |
| | | 50 |
| | | 51 |
| | | 52 |
| | | 53 |
| | | 54 |
| | | 55 |
| | | 56 |
| | | 57 |
| | | 58 |
| | | 59 |
| | | 60 |
| | | 61 |
| | | 62 |
| | | 63 |
| | | 64 |
| | | 65 |
| | | 66 |
| | | 67 |
| | | 68 |
| | | 69 |
| | | 70 |
| | | 71 |
| | | 72 |
| | | 73 |
| | | 74 |
| | | 75 |
| | | 76 |
| | | 77 |
| | | 78 |
| | | 79 |
| | | 80 |
| | | 81 |
| | | 82 |
| | | 83 |
| | | 84 |
| | | 85 |



| X10 QE1操作机构 | | | |
|-------------|----|-----|----|
| 对侧 | 线号 | 端子号 | 对侧 |
| | | 1 | |
| | | 2 | |
| | | 3 | |
| | | 4 | |
| | | 5 | |
| | | 6 | |
| | | 7 | |
| | | 8 | |
| | | 9 | |
| | | 10 | |



| 序 号 | 符 号 | 名 称 | 规格及型号 | 数 量 | 安 装 地 点 | 备 注 |
|-----|---------|--------|-------------------|-----|---------|-----|
| 1 | JK1 | 交流断路器 | 20A-3P+0F, AC380V | 1 | | |
| 2 | JK2~JK3 | 交流断路器 | 6A-1P+0F, AC220V | 2 | | |
| 3 | ZK1~ZK3 | 直流断路器 | 10A-2P+0F, DC220V | 6 | | |
| 4 | ZK4 | 直流断路器 | 16A-2P+0F, DC220V | 1 | | |
| 5 | L | 照明灯 | AC220V | 1 | | |
| 6 | WSK | 温度度控制器 | AC220V | 1 | | |
| 7 | X11 | 电流端子 | | N | | |
| 8 | X0~X10 | 普通端子 | | N | | |
| 9 | 连接片 | | | N | | |

端子箱元件接线图